



Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs)
page 1 of 6




Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs) page 2 of 6




Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs) page 3 of 6



Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs) page 4 of 6



Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs)
page 5 of 6



Common Violations of the 1977 National Building Code of the Philippines (NBCP) that are not being addressed (or cannot be rectified) by the concerned Offices of Building Officials (OBOs) and/or City/Municipal Engineers (CE/ME) and/or their respective Local Government Units (LGUs) page 6 of 6